

	Type	Hits	Search Text
1	BRS	746	408/97.ccls. or 408/103.ccls.
2	BRS	642	408/115R.ccls. or 408/241b.ccls.
3	BRS	1249	S2 or S1
4	BRS	826	B23B049/02.ipc.
5	BRS	724	S4 not S3
6	BRS	192	408/72B.ccls. or 408/115B.ccls.
7	BRS	97	S6 not S3
8	BRS	72	S7 not S5
9	BRS	100	drill and (oblique adj hole)
10	BRS	84	drilling and (oblique adj hole)
11	BRS	124	S10 or S9
12	BRS	5374	hole same crankshaft
13	BRS	560	S12 and drill\$3
14	BRS	559	S13 not S5

	DBs	Time Stamp	Comments	Error Definition
1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 12:49		
2	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 12:49		
3	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 21:04		
4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 15:13		
5	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 15:13		
6	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 16:54		
7	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 16:54		
8	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 16:57		
9	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 16:58		
10	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 16:58		
11	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 17:05		
12	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 17:05		
13	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 17:06		
14	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 17:06		

	Type	Hits	Search Text
15	BRS	556	S13 not S3
16	BRS	780	b23b047/28.IPC.
17	BRS	767	S16 not S6
18	BRS	694	S17 not S5
19	BRS	586	S18 not S3
20	BRS	1	B23B049/000.ipc.
21	BRS	1760	B23B049/00.ipc.
22	BRS	1684	S21 not S3
23	BRS	1667	S22 not S5
24	BRS	1664	S23 not S6
25	BRS	1400	S24 not circuit
26	BRS	1379	B23B045/14.ipc.
27	BRS	1302	S26 not S3
28	BRS	1270	S27 not S5

	DBs	Time Stamp	Comments	Error Definition
15	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 17:06		
16	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 17:36		
17	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 17:36		
18	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 17:37		
19	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 17:58		
20	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 17:58		
21	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 17:58		
22	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 17:59		
23	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 17:59		
24	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 18:28		
25	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 19:14		
26	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 19:14		
27	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 19:14		
28	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 19:14		

	Type	Hits	Search Text
29	BRS	1264	S28 not S6
30	BRS	1237	S29 not S16
31	BRS	1182	S30 not S21
32	BRS	1124	S31 not circuit
33	BRS	44	S32 and bushing
34	BRS	388	S32 and guide
35	IS&R	1	("d295016").PN.
36	IS&R	2	("3804546").PN.
37	BRS	9	"3804546".uref.

	DBs	Time Stamp	Comments	Error Definition
29	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 19:15		
30	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 19:15		
31	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 19:15		
32	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 20:11		
33	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 20:13		
34	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 20:14		
35	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 20:30		
36	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 21:19		
37	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/08/06 21:19		